

FIG. 1(a) FIG. 1(b) FIG. 1(c) FIG. 1(d)

FIG. 1(a)




FIG. 1(b)




FIG. 1(c)




FIG. 1(d)




FIG. 2




FIG. 3(a)




FIG. 3(b)




FIG. 4




FIG. 5




FIG. 500 "SEE FIG. 500"

FIG. 6




FIG. 7




FIG. 7

FIG. 8




FIG. 9




FIG. 10

FIG. 10







FIG. 11



A. STENT, OVER DELIVERY SYSTEM
(NOT DEPLOYED)



B. STENTS ALONE
(NOT DEPLOYED)



C. STENTS EXPANDED




FIG 14

D. ONE STENT LAYOUT

- Side Access.
- BIF.

FIG 14 - SEE FIG 13

FIG 15






FIG 16



91






Fig. 19



09274335 . 060401